

Software update

CAR 60



TEXA

IDC4 CAR 60.0.0 SOFTWARE UPDATE

The new **software update CAR 60** offers a large number of diagnostic developments and special functions that guarantee the opportunity to work with professionalism to the mechanics who use TEXA's diagnostic solutions; this also thanks to the possibility to consult technical information that is essential in order to complete all workshop operations.

CAR 60 includes several new selections, for the major makes on the international market, among which: **BENTLEY, AUDI, FERRARI, FORD, HYUNDAI, JAGUAR, JEEP, KIA, LAND ROVER, LEXUS, MERCEDES-BENZ, MINI, SCION, TOYOTA, VOLKSWAGEN.**

Following are just a few of the many new diagnostic features included in this CAR software version that take into consideration the functions mostly requested by workshops and that are dedicated to the most widespread makes:

VEHICLE MAINTENANCE NEWS

Differential pressure sensor adaptation

VOLKSWAGEN: Vento [10>] (60) 1.6 16v TDI.

Oil change

JEEP: Renegade [14>] (BU) 1.6 16v MJ, 2.0 16v MJ 4x4.

Electronic steering column lock open status check

HYUNDAI: Accent V [11>] (RB) 1.4i 16v Mpi Kat; Grand i10 [14>] (BA) 1.0i 12v Kat; i20 [15>] (GB/IB) 1.4i 16v Kat; Tucson [15>] (TL) 1.6i 16v GDi Kat; Xcent [14>] (BA) 1.2i 16v Kat.

KIA: Sorento III [15>] (UM) 2.2 16v CRDi 4WD, 2.4 16v Turbo Kat, 3.3i V6 Kat.

Complete service

MERCEDES-BENZ: C [14>] (205) T 400i Kat 4 Matic; GLE [15>] (292) Coupé 320i Kat 4 Matic; S [13>] (222) L 500i Kat 4 Matic, 63i AMG Kat.

Zero point adjustment

MERCEDES-BENZ: GL/GLS [12>] (166) 350 CDI 4 Matic, 350 D BlueTEC 4 Matic, 400i Kat BlueEFFICIENCY 4 Matic; ML/GLE [11>] (166) 63i AMG S Kat 4 Matic; SL [12>] (231) 350i Kat BlueEFFICIENCY; SLK/SLC [11>] (172) 55i AMG Kat.

For further details on these functions and on their applicability to vehicles, visit:
www.texa.com/coverage

Vehicle check reset

BMW: 2 [15>] (F46) Gran Tourer 218i Kat, 220i Kat, i8 [14>] (I12) 1.5i Turbo Kat eDRIVE.
MINI: Mini (F55/F56) [14>] Cooper 1.5i 12v Kat, Cooper S 2.0i 16v Turbo Kat.

Electro-mechanical parking brake function test

VOLKSWAGEN: Touran [15>] (5T) 1.2i 16v TSI Kat BlueMotion, 1.4i 16v TSI Kat BlueMotion, 1.6 16v TDI BlueMotion, 2.0 16v TDI BlueMotion.

ADJUSTMENTS AND CODING NEWS

Mirror Lowering with Reverse Rear

VOLKSWAGEN: Touran [15>] (5T) 1.2i 16v TSI Kat BlueMotion, 1.4i 16v TSI Kat BlueMotion, 2.0 16v TDI BlueMotion.

Control unit resetting

BMW: 2 [14>] (F22) 218 d, 218i Kat, 220 xd, 225 d, 228xi Kat.

ECU accessibility

FERRARI: 575M [03>07] (F133) 5.8i V12 Kat, 575M [04>06] (F133) Superamerica 5.8i V12 Kat, Enzo [02>05] (F140) 6.0i V12 Kat, F430 [05>09] (F131) 4.3i V8 Kat, F430 [05>09] (F131) Spider 4.3i V8 Kat, F430 [07>09] (F131) Challenge 4.3i V8 Kat.

Stop-start activation

FORD: B-Max [12>] (JK) 1.4i 16v Kat; Focus [15>] (DYB) Facelift 1.5i 16v Kat Ecoboost, Facelift Turnier 1.5i 16v Kat Ecoboost; Kuga [13>] (DM2) 1.5i 16v Kat Ecoboost, 1.5i 16v Kat Ecoboost 4x4.

Boost pressure regulation check

AUDI: A4 [07>15] (8K2) 2.0 16v TDI, 2.0 16v TDI quattro, Avant Allroad 2.0 16v TDI quattro; A5 [07>] (8T3) Coupé 2.0 16v TDI; Q5 [08>] (8RB) 2.0 16v TDI quattro.

Throttle valve actuator

LAND ROVER: Discovery Sport [15>] (LB) 2.2 SD4; Freelander II [07>13] (LF) 2.2 eD4, 2.2 SD4, 2.2 TD4.

Gateway initialization

LEXUS: ES (V6) 350 [12>] 3.5i V6 24v Kat; GS (L1) 350 [12>] 3.5i V6 24v Kat, HS (F1) 250h [09>] 2.4i 16v Kat; IS (E3) 250 [13>] Sedan 2.5i Kat; LFA (A1) [10>12] 4.8i V10 Kat; LS (F4) 460 [07>] 4.6i V8 Kat; NX (Z1) 300h [14>] 2.5i 24v Kat; RC (C1) F [15>] 5.0i V8 Kat.

Wireless door lock diagnosis mode

TOYOTA: 4-Runner V [09>] (N28) 2.7i 16v Kat; Auris [13>] (E18) 1.6 D-4D, Auris Wagon 1.2i 16v Turbo Kat; Avalon IV [13>] (X40) Hybrid 2.5i 24v Kat; Camry [06>11] (V4) 2.4i 16v Kat; Corolla [13>] (E18) 2.0i 16v Kat; Highlander II [07>13] (U4) 2.7i 16v Kat; RAV4 [12>14] (A3) EV electric; Sequoia II [08>] (K6) 4.6i V8 32v Kat.

NEW FAST-FIT FEATURES

Auxiliary headlight activation

HYUNDAI: i30 [15>] (GD) Facelift 1.6i 16v Turbo GDi Kat, Kombi Facelift 1.4 16v CRDi; i40 [15>] (VF) Sedan Facelift 2.0i 16v Mpi Kat; ix35/ Tucson [09>15] (EL/LM) 2.0i 16v GDi Kat
KIA: Cee'd [15>] (JD) Facelift 1.6i 16v GDi Kat, Sportswagon Facelift 1.0 12v Turbo GDi Kat, Sportswagon Facelift 1.4i 16v CCVT Kat GPL.

New battery adaptation

VOLKSWAGEN: Touran [15>] (5T) 1.2i 16v TSI Kat BlueMotion, 1.4i 16v TSI Kat BlueMotion, 1.6 16v TDI BlueMotion, 2.0 16v TDI BlueMotion.

Accumulated distance since last oil change

BENTLEY: Mulsanne [11>] 6.8i V8 Kat.
AUDI: Q3 [11>] (8UB) 1.4i 16v TFSI Kat.
VOLKSWAGEN: Amarok [10>] (2H) 2.0i TFSI Kat 4Motion; Eos [11>] (1F8) 1.4i 16v TSI Kat BlueMotion; Golf VI [08>13] (5K1) 1.2i 16v TSI Kat BlueMotion; Jetta [10>] (162) 1.2i 16v TSI Kat BlueMotion; Passat CC [12>] (358) 1.4i 16v TSI Kat BlueMotion; Polo [09>14] (6R1) 1.2i 12v Kat; Tiguan [12>] (5N2) 1.4i 16v TSI Kat; Touran [15>] (5T) 2.0 16v TDI BlueMotion. TSI Kat BlueMotion; Polo [09>14] (6R1) 1.2i 12v Kat; Tiguan [12>] (5N2) 1.4i 16v TSI Kat; Touran [15>] (5T) 2.0 16v TDI BlueMotion.

MAIN IMPLEMENTED FUNCTIONS DIVIDED BY TYPE

Keys/Remote control

BMW: 2 [14>] (F45) Active Tourer 214 d.
SCION: iQ [12>] (J10) EV electric; TC [11>] (T20) 2.5i 16v Kat; XB [07>] (E15) 2.4i 16v Kat; XD [07>14] (P11) 1.8i 16v Kat.
TOYOTA: Sequoia II [08>] (K6) 5.7i V8 32v Kat; Sienna III [10>] (L3) 2.7i 16v Kat, 3.5i V6 24v Kat; Tundra II [07>] (K5) 4.0i V6 24v Kat.

Particulate filter regeneration

AUDI: A4 [07>15] (8K2) 2.0 16v TDI, 2.0 16v TDI quattro, A4 [07>15] (8K5) Avant 2.0 16v TDI; A4 [09>15] (8KH) Avant Allroad 2.0 16v TDI quattro; A5 [07>] (8T3) Coupé 2.0 16v TDI; Q5 [08>] (8RB) 2.0 16v TDI quattro.
FORD: Focus [15>] (DYB) Facelift 2.0 16v TDCi;

Kuga [13>] (DM2) 2.0 16v TDCi, 2.0 16v TDCi 4x4; Mondeo V [15>] 2.0 16v TDCi, Turnier 2.0 16v TDCi.
HYUNDAI: Accent V [11>] (RB) 1.6 16v CRDi; i20 [15>] (GB/IB) 1.4 16v CRDi; i30 [15>] (GD) Facelift 1.4 16v CRDi; i40 [15>] (VF) Sedan Facelift 1.7 16v CRDi; Xcent [14>] (BA) 1.1 12v CRDi.
JEEP: Renegade [14>] (BU) 1.6 16v MJ, 2.0 16v MJ 4x4.
MERCEDES-BENZ: C [14>] (205) T 300 CDI BlueTEC Hybrid; CLS [11>] (218) Coupé 220 D BlueTEC; E [02>09] (211) 420 CDI; GLC [15>] (253) 250 D 4 Matic; ML [05>11] (164) 420 CDI 4 Matic; S [05>13] (221) 320 CDI.
VOLKSWAGEN: Touran [15>] (5T) 1.6 16v TDI BlueMotion; Vento [10>] (60) 1.6 16v TDI.

Instrument panel language change

BENTLEY: Mulsanne [11>] 6.8i V8 Kat

AUDI: Q3 [11>] (8UB) 1.4i 16v TFSI Kat, 2.0 16v TDI, 2.0 16v TDI quattro, RSQ3 [13>] (8UB) 2.5i 20v TFSI Kat quattro

Battery replacement

BMW: i8 [14>] (I12) 1.5i Turbo Kat eDRIVE

JAGUAR: XJ [10>] (X351) 3.0i V6 Kat AWD, XJ [10>] (X351) 5.0i V8 Kat, XJ [13>] (X351) R 5.0i V8 Kat

MINI: Mini (F55/F56) [14>] Cooper SD 2.0 D; One 1.2i Kat, One D 1.5 D

Brake pad replacement

HYUNDAI: i30 [15>] (GD) Facelift 1.4 16v CRDi; i40 [15>] (VF) Sedan Facelift 2.0i 16v Mpi Kat.

JAGUAR: XF [08>15] (X250) 2.0i 16v Turbo Kat, 3.0i V6 Kat, 4.2i V8 Kat; XF [12>15] (X250) Sportbrake 3.0 V6 D, XF [13>15] (X250) R-S 5.0i V8 Kat, R-S Sportbrake 5.0i V8 Kat

KIA: Cee'd [15>] (JD) Facelift 1.6i 16v GDi Kat, Sportswagon Facelift 1.0 12v Turbo GDi Kat

Transport mode

AUDI: Q3 [11>] (8UB) 2.0i 16v TFSI Kat quattro; RSQ3 [13>] (8UB) 2.5i 20v TFSI Kat quattro.

BMW: 2 [14>] (F22) 218 d, 225 d, 228xi Kat.

JAGUAR: XJ [10>] (X351) 3.0i V6 Kat AWD, 5.0i V8 Kat.

VOLKSWAGEN: Eos [11>] (1F8) 1.4i 16v TSI Kat BlueMotion; Jetta [10>] (162) 1.2i 16v TSI Kat BlueMotion; Lamando [15>] 1.4i TFSI Kat, 1.8i TFSI Kat; Passat CC [12>] (358) 1.4i 16v TSI Kat BlueMotion.

TPMS Tyre Pressure Monitoring System

FERRARI: 575M [03>07] (F133) 5.8i V12 Kat, [04>06] (F133) Superamerica 5.8i V12 Kat; Enzo [02>05] (F140) 6.0i V12 Kat; F430 [05>09] (F131) 4.3i V8 Kat, F430 [05>09] (F131) Spider 4.3i V8 Kat, F430 [07>09] (F131) Challenge 4.3i V8 Kat.

HYUNDAI: Azera [11>] (HG) 3.3i V6 Kat; Grand Santa Fe [13>] (NC) 2.2 16v CRDi 4x4; Grandeur [11>] (HG) 3.0i V6 Kat; i20 [15>] (GB/IB) 1.1 12v CRDi; i30 [15>] (GD) Kombi Facelift 1.6i 16v Turbo GDi Kat; i40 [11>14] (VF) Kombi 1.6i 16v GDi Kat; ix35/Tucson [09>15] (EL/LM) 2.0i 16v GDi Kat 4x4; Sonata VII [15>] (LF) 1.6i 16v Kat; Sonata VII [15>] (LF) Hybrid 2.0i 16v GDi Kat Hybrid; Tucson [15>] (TL) 1.6i 16v GDi Kat.

Tyre management

JEEP: Renegade [14>] (BU) 1.4i 16v MultiAir2 Turbo Kat, 1.4i 16v MultiAir2 Turbo Kat 4x4, 1.6 16v MJ, 1.6i 16v E-TorQ Kat, 2.0 16v MJ 4x4, 2.4i 16v MultiAir2 Kat, 2.4i 16v MultiAir2 Kat 4x4.

TOYOTA: Auris [13>] (E18) 1.6 D-4D, Wagon 1.2i 16v Turbo Kat.

Driver assistance systems

AUDI: A6 [11>] (4G2) 2.0 16v TDI, 2.0 16v TDI quattro, 2.0i 16v TFSI Kat, 2.0i 16v TFSI Kat Hybrid, 3.0 V6 TDI, 3.0 V6 TDI quattro, Avant Allroad 3.0 V6 TDI quattro; A7 [10>] (4GA) Sportback 2.5i V6 FSI Kat quattro, 2.8i V6 FSI Kat quattro; A8 [10>] (4H2) 3.0 V6 TDI, 3.0 V6 TDI quattro, 3.0i V6 24v TFSI Kat quattro, 4.0i V8 TFSI Kat quattro, 4.2 V8 TDI quattro; Q3 [11>] (8UB) 2.0i 16v TFSI Kat quattro; RS6 [13>] (4G5) Avant 4.0i V8 TFSI Kat quattro.

BMW: 2 [14>] (F45) Active Tourer 214 d

HYUNDAI: Grand Santa Fe [13>] (NC) 2.2 16v CRDi 4x4; Sonata VII [15>] (LF) 2.4i 16v Mpi Kat,

Sonata VII [15>] (LF) Hybrid 2.0i 16v GDi Kat Hybrid

MERCEDES-BENZ: GLE [15>] (292) Coupé 320i Kat 4 Matic, 450i Kat 4 Matic, 63i AMG Kat 4 Matic

VOLKSWAGEN: Golf VII [14>] (BE1) EV electric, Golf VII [15>] (AM1) Sportsvan 1.2i 16v TSI Kat BlueMotion, Passat B8 [14>] (3G5) Variant 2.0 16v TDI BlueMotion; Touran [15>] (5T) 1.2i 16v TSI Kat BlueMotion.

Video camera calibration*

BMW: 2 [14>] (F45) Active Tourer 214 d.

HYUNDAI: Grand Santa Fe [13>] (NC) 2.2 16v CRDi 4x4; Sonata VII [15>] (LF) 2.4i 16v Mpi Kat, Hybrid 2.0i 16v GDi Kat Hybrid.

MERCEDES-BENZ: GLE [15>] (292) Coupé 320i

Kat 4 Matic, 350 D 4 Matic, 400i Kat 4 Matic, 450i Kat 4 Matic, 63i AMG Kat 4 Matic.

VOLKSWAGEN: Touran [15>] (5T) 1.2i 16v TSI Kat BlueMotion, 1.4i 16v TSI Kat BlueMotion, 1.6 16v TDI BlueMotion, 2.0 16v TDI BlueMotion.

*an external calibration device could be needed for some vehicle models.

Parking assistance

BMW: 2 [14>] (F22) 228xi Kat, 2 [14>] (F23) Cabrio 218d, 2 [14>] (F45) Active Tourer 214 d.

MERCEDES-BENZ: C [14>] (205) 160i Kat; S [13>] (222) 300 CDI BlueTEC Hybrid; S [14>] (217) Coupé 500i Kat.

VOLKSWAGEN: Lamando [15>] 1.8i TFSI Kat; Touran [15>] (5T) 1.2i 16v TSI Kat BlueMotion.

NOTE: The list is only a small part of the many new features that TEXA developed and included in this version. Major details regarding the functions mentioned above and their applicability to the vehicles are available in the IDC4E software in the DOCUMENTATION menu and at the website www.texausa.com/coverage; here you can find the complete list of the new features introduced starting from this update in order so you can fully understand the developments that make TEXA's tools ideal workmates!

COMPATIBILITY OF TEXA'S IDC4E SOFTWARE AND THE NEW WINDOWS 10 OPERATING SYSTEM

In order to make the IDC4E software compatible with the new software technologies introduced by Microsoft in the new Windows 10 operating system, we wish to inform you that:

- **for the 64-bit version of Windows 10** the IDC4E versions **CAR 60, TRUCK 38, BIKE 25, MARINE 11, OHW 14** are compatible and can be installed.

- **for the 32-bit version of Windows 10** the IDC4E versions **CAR 60, TRUCK 39, BIKE 25, MARINE 11, OHW 14** can be installed but some accessory software functions are still not guaranteed. For this reason, we recommend staying connected to the Internet in order to receive the updates. If upgrading the PC from **Windows 7 or 8 to the 32-bit version of Windows 10** with IDC4E already, it must be reinstalled at the end of the transfer.

EXTENDED COVERAGE OF MAKES

VERSION 60

CARS AND LIGHT COMMERCIALS

AUDI
BMW
CHRYSLER
DAIHATSU
DODGE
FORD
HUMMER
HYUNDAI

JAGUAR
JEEP
KIA
LAND ROVER
LEXUS
LOTUS
MAYBACH
MAZDA

MERCEDES-BENZ
MINI
PORSCHE
SCION
SMART
TOYOTA
VOLKSWAGEN
VOLVO

SUPERCAR

ALFA ROMEO
ASTON MARTIN
BENTLEY
CHEVROLET
DODGE
FERRARI
LAMBORGHINI
MASERATI

MORGAN
PAGANI
PORSCHE
ROLLS-ROYCE

LEGEND

	Brands that offer updates in this version		Brands that do not offer updates in this version
--	---	---	--

This document is strictly confidential. All copying, in part or in whole, is strictly forbidden without the prior authorisation of TEXA S.p.A. Future specifications, descriptions and appearances may vary with respect to this brochure. TEXA S.p.A. reserves the right to modify its products without prior notice.

WARNING

The trademarks and logos of vehicle manufacturers in this document have been used exclusively for information purposes and are used to clarify the compatibility of TEXA products with the models of vehicles identified by the trademarks and logos. Because TEXA products and software are subject to continuous developments and updates, upon reading this document they may not be able to carry out the DIAGNOSTICS of all the models and electronic systems of each vehicle manufacturer mentioned within this document. References to the makes, models and electronic systems within this document must therefore be considered purely indicative and TEXA recommends to always check the list of the "Systems that can be diagnosed" of the product and/or software at TEXA authorized retailers before any purchase. **The images and the vehicle outlines within this document have been included for the sole purpose of making it easier to identify the vehicle category (car, truck, motorbike, etc.) for which the TEXA product and/or software is intended.** The data, descriptions and illustrations may change compared to those described in this document. TEXA S.p.A. reserves the right to make changes to its products without prior notice.



www.texausa.com



northamerica@texa.com



www.facebook.com/texausa



www.twitter.com/texacom



www.youtube.com/texacom



The BLUETOOTH brand is the property of Bluetooth SIG, Inc., U.S.A., and is used by TEXA S.p.A. under license.

Copyright TEXA S.p.A. - 03/2016 - NA

MADE IN ITALY

